



H247

PLANT PRE-DELIVERY INSPECTION SHEET PDI -

H+S ☒

RT ☒

FE ☒

ROTATE ☒

BIO OIL ☒

Make / Model	2X130 - 7	Date:	18/06/2026
Fleet Number	H247		
Hour Meter	4056 hrs		

Machine Serviced	250 ☐ 500 ☐ 1000 ☐	Service Computer reset ☐	Service sticker updated ☐
------------------	---	---	--

Service due	4140 hrs		
-------------	----------	--	--

Plant item	OK	Defect	Fuel / Fluids	OK	Defect
Rams / bushings	✓		Fuel Level	100%	
Cab Guards/Covers	N/A		Fuel connectors & pipes	✓	
Lifting eye / points	✓		Engine Oil Level	100%	
Cab glass	✓		Coolant Level	100%	
Chassis bolts & security	✓		Hydraulic fluid level	100%	
Seat secure & fully adjustable	✓		Washer fluid level	100%	
Tracks	✓		Ad-blue level	N/A	
Blade / stabilizers if fitted	N/A		Refuelling Hose - present	✓	
Seat & Seat Belt	✓				
Steering if applicable	N/A				
Brakes as appropriate	N/A				
Bodywork	✓				
Operating Controls	✓				
Warning Lights	✓				
Gauges/Instruments	✓				
Railings / boxing ring	✓				
Fan & other belts / chains	✓				
Fuel cap secured	✓				
Lenses & mirrors	✓				
Rear & 360° cameras	✓				
Horn	✓				
Travel alarm	✓				
Lights / Beacons	✓				
Obvious Leaks	N/A				
Safety pins & bolts	✓				
Floor mats/ Air freshener	✓				

Electric		
Cable Connections	✓	
General Cleanliness	✓	
Battery Security	✓	

Other Checks		
Front left wheels		
Front right wheels		
Rear left wheels		
Rear right wheels		

Defects / Service Details / Notes ~~* LHS CAMERA MISSING *~~
ALL CHECKED OVER. ALL GREASED AND CLEANED
AROUND.

Engineers name: Ae	Signature: Nty Bionny
-----------------------	--------------------------